

JUSTIFICATION FOR SOLE SOURCE/BRAND NAME: (Simplified Acquisitions <\$150K)

The service or material listed on V21955-6068-S303 is sole source and competition is precluded for reasons indicated below. There are no substitutes available for this material or service.

**Restricted to the following source.** Provide original manufacturer's name. (If a sole source manufacturer distributes via dealers, ALSO provide dealer information.)

Manufacturer: EDRO

Manufacturer POC & phone nbr. 1-800-628-6434

Mfr. Address: PO Box 308 East Berlin, CT 06023

Dealer / Rep:

Dealer / Rep address / phone nbr.

Description of the item or service required, the estimated cost, and required delivery date.

- Procure one (1) DynaWash washer extractor (P/N DW600PNSWE-24B and one (1) DynaWash washer extractor (P/N DW600PNSWE-24BER) and miscellaneous hardware for install. Provide approx. 240 hours of labor to install aforementioned items onboard USS WINSTON S. CHURCHILL (DDG 81). Lead time is approx. 10 weeks, but faster delivery time is requested and desired if possible.

Specific characteristics of the material or service that limit the availability to a sole source (unique features, function of the item, etc.). Describe in detail why only this suggested source can furnish the requirements to the exclusion of other sources.

- EDRO is the OEM for the product. Warranty on equipment is void if installed by government entity or other private company that is not an EDRO certified dealer/distributor/service rep.

The requested material or service represents the minimum requirements of the government.

- EDRO DynaWash washer extractor P/N DW600PNSWE series is required to replace the existing one onboard the ship as this is the only shipboard approved washer that can support a crew of 300 personnel.

CHECK & FILL IN ALL APPLICABLE BLANKS BELOW

The material/service must be compatible in all aspects (form, fit and function) with existing systems presently installed/performing. Describe the equipment/function you have now and how the new item/service must coordinate, connect, or interface with the existing system.

- The current washer-extractors have been in service for 18 years and are severely degraded (catastrophic main bearing and seal failure). Typical service life for this equipment is 20 years and would be more cost effective to replace the washers vice repair.

\_\_\_\_ A patent, copyright or proprietary data limits competition. The proprietary data is \_\_\_\_\_

  X   These are "direct replacements" parts/components for existing equipment.

\_\_\_\_ Other information to support a sole source buy:

I CERTIFY THAT STATEMENTS CHECKED, AND INFORMATION PROVIDED ABOVE, ARE COMPLETE AND CORRECT TO THE BEST OF MY KNOWLEDGE. I UNDERSTAND THAT THE PROCESSING OF THIS SOLE SOURCE JUSTIFICATION PRECLUDES THE USE OF FULL AND OPEN COMPETITION.

A handwritten signature in dark ink, consisting of stylized, overlapping loops and a trailing flourish.